

EVIDENCE OF IMPROPER SULLAGE DISPOSAL

- A black hose could be seen hanging over the rear of two docked vessels
- Sullage can be seen streaming from the hose into the water
- A distinct smell of sewage can be detected
- A sheen can be seen on the surface of the water

